FIG. 1

Sample #1 Surface at 40X After 48 Hours at 150C




FIG. 2

Sample 3 Surface Photo 40X After 49 hours at 150C



Sample 3 After 48 Hrs./159C Corner of Plaque 40X lon rate a catalina. #3 Control 48Hrs./150C 40X Corner Crazing/Very Byxtle


FIG. 4

Sample 4 Corner Shot 40X 48 Hours at 150C



FIG. 5

Sample 4 Surface Photo 40X After 48 Hrs./150C



and the second

FIG. 6

!,

Corner View After 48 Hrs./150C Sample 3 versus 4

#4 Control 48Hrs./150C 40X Corner Crazing/Nery Brittle Another View Washed Sufur Black #3 Control 48Hrs./150C 40X Corner Crazing/Very Brixtle

Onwashed Suffer Black